

Service
Service
Service

FL1.1

AC

92.03

Service Information

Software overview FL1.1

In this service information bulletin an overview is given of the software used up until now in the FL1.1. At the same time the AG code with which the software was introduced and the modifications to the previous versions is also given.

Tabl

Opt
0
1
2
4
8
16
32
64
128
Opt
0
1
2
4
8
16
32
64
128

Table 1

Optioncode 1	
0	Front end = FQ816/IF
1	Front end = FQ844
2	Front end = FQ816/ME/IF
4	Front end = FQ816/MF/IF
8	PIP module fitted
16	NTSC-M reception possible
32	SECAM DK module fitted
64	NICAM module fitted
128	second front end for PIP fitted
Optioncode 2	
0	not used
1	not used
2	not used
4	100 Hz box
8	Scandinavian languages
16	NICAM with PCF8574A
32	not used
64	not used
128	not used

Table 2

Optioncode 1	
0	Front end = FQ816/IF
1	Front end = FQ844
2	Front end = FQ816/ME/IF
4	Front end = FQ816/MF/IF
8	PIP module fitted
16	NTSC-M reception possible
32	SECAM DK module fitted
64	NICAM module fitted
128	second front end for PIP fitted
Optioncode 2	
0	IC7175 not present on SSP
1	IC7175 present on SSP
2	auto digit entry
4	100 Hz box
8	not used
16	NICAM with PCF8574A
32	ECO NICAM module present
64	not used
128	comb filter present

Software overview I

Factory code	Service code	AG code	Description
3104 317 1240.1	4822 212 23705	AG00	V6 version Remark: - "child lock on" indication on the Option code: see table 1
3104 317 1240.2	4822 212 23705	AG00	V9 version Remark: - dealer remote version Option code: see table 1
3104 317 1240.3	4822 212 23705	AG01	V13 version Remark: - reduction of menu contrast Option code: see table 1
3104 317 2386.1	4822 212 23894	AG02	V16 version Remark: - possibility to use ECO NICAM - possibility to use SSP (.4), mc - 16/9 status on both scart connectors pin 8 scart 0 - 2V 4.5 - 7V 9.5 - 12V - one/two digit entry - removal of the installation menu - longer waiting time before "no signal" - waiting time introduced on the menu - languages in one cluster, option code Option code: see table 2
3104 317 2386.2	4822 212 23894	AG07	V20 version Remark: - "free bus" routine to prevent false combination of DVTB and ECO - set no longer in stand-by after 30 min - sound specification modification 1. When the broadcast is not in Depending on the signal level displayed on the screen 2. Possibility to switch between broadcast is not in stand-by broad cast "digital" Option code: see table 2
3104 317 2386.3	4822 212 23894	AG07	V26 version Remark: - condition for software protection condition is still present after 30 min - modifications in TOP-TXT Option code: see table 2
3104 317 2386.4	4822 212 23894	AG07	V28 version Remark: - line "e" now always appears in - the menu button now has an icon - if external breaks through via P+ command instead of re-station Option code: see table 2

re overview FL1.1

	Replaced by
<p>back on" indication on the screen : 1</p>	4822 212 23894
<p>remote version : 1</p>	4822 212 23894
<p>on of menu contrast : 1</p>	4822 212 23894
<p>ity to use ECO NICAM, modify option code 2 ity to use SSP'(4), modify option code 2 atus on both scart connectors art 0 - 2V : no video 4.5 - 7V : 16/9 9.5 - 12V : 4/3 digit entry l of the installation menu with "DOS" button waiting time before "no video" is displayed on the screen time introduced on the "the stable osd" line to avoid the picture rolling in 100Hz ges in one cluster, option code 2 no longer ignored : 2</p>	
<p>s" routine to prevent false error codes being received on the IC bus due to the ation of DVTB and ECO NICAM onger in stand-by after 10 minutes on external without picture : specification modification 1. When the broadcast is BG, line "e" always appears in the sound menu. Depending on the broadcast either "mono", "stereo" or "digital" will be displayed on the screen. 2. Possibility to switch between stereo or mono and digital or analogue, even if the broadcast is not in stereo or NICAM. If analogue is selected for a NICAM broad cast "digital sound available" no longer appears on the screen. : 2</p>	
<p>n for software protection is: TDA8417 + TDA8425 + TDA4680. If the error n is still present after 300ms the set goes into software protection ations in TOP-TXT : 2</p>	
<p>now always appears in the sound menu and not only during BG broadcasts u button now has an on/off switch function al breaks through via status the set will continue further following the mand instead of re-starting at the beginning : 2</p>	