


Notes & Errata

3-Way Active Crossover, January 2003: the equation for the crossover frequency shown in Fig.4 is incorrect. It shows the whole bottom line within the square root symbol whereas only the 2 should be within the square root.

Simple DC Power Supply, March 2004: a track is missing on the PC board layout between the anode of D5, cathode of D6 and the output of REG1. The corrected PC board pattern is shown at right.

This error was also present in the PSU.ZIP design files mentioned in the article. An updated version can be downloaded from www.siliconchip.com.au

Current Clamp Adaptor For DMMs, September 2003: as presented, the clamp adaptor is not suitable for use



with 240VAC mains when the wiring is uninsulated. To make it safe, both the metal clip and the toroid must have insulating coatings.