

20-10-18

ENGINEERING CHANGE REQUEST ECO # 8820

TITLE POWER SUPPLY MODIFICATION / CORRECTION

PT OR ASSY PCB ASSY (780011) PRODUCT B500B, G500S

DESCRIBE PROBLEM (ATTACH ADDITIONAL DOCUMENTATION IF NECESSARY)

POWER SUPPLY ALUMINUM ELECTROLYTICS FAIL. NO VOLTAGE MARGIN.

NON-UL APPROVED GROUNDING NEEDS TO BE CORRECTED.

NAME OF REQUESTOR D. W. H.

DATE 2/25/92

APPROVED ☐ DENIED ☒ BY D. H.

DATE 2/26/92

ENGINEERING CHANGE ORDER

ECO # 8820 TITLE POWER SUPPLY MODIFICATION

PT OR ASSY AFFECTED 780011 + 780054 IN B500, G500

DETAILS

DO NOT USE OR STUFF POWER SUPPLY PCB SECTION ON. BREAK AWAY PCB. (PCB 6800B3, B584A; ASSY 780011) REPLACE WITH ASSY 780054.

PLACE 6800B3 (B584A) ON PURCHASING HOLD.

ORIGIN (ATTACH A SEPERATE SHEET IF NECESSARY)

REMOVE POWER SUPPLY ASSEMBLY AND ASSOCIATED HARDWARE. REPLACE WITH NEW SUB-ASSY (780054). SEE ATTACHED DWGS, B626C, B630C, B585C

ACTIVITY: NEW PRODUCTION ☒ WORK IN PROGRESS ☒

FINISHED GOODS ☒ FIELD RETURNS ☒

DOCUMENTATION CHANGE ONLY ☐

PRINTING SERIAL NUMBER



<http://www.adadepot.com>