

Auto Electronics (October 1996): In Fig.7, on page 45, the Hall Sensor plates for XF Falcon EST and EFI (EECIV) systems were unfortunately swapped. The corrected diagram is shown above.