AM/FM/CW Scanning HF/VHF RF Signal Generator, June & July 2019: some constructors have described erratic operation of the rotary encoder. The designer has tracked this down to variations in the internal RC oscillator frequency of the ATmega328P microcontroller (IC1). Revised software (V11) is available for down-

load from the Silicon Chip website which fixes this. This new version will also be used to program any chips ordered from now on.