

Service
Service
Service

FL1.0

AC

91.04

Service Information

Overview of the manual and AG codes of chassis FL1.0

MANUAL CODE	AG CODE	DATE	REASON	SERVICE INFORMATION
AA	00	start		
AA	01	1990 Week 50	New layout PIP panel, 5V safety resistor from SSP to PIP panel.	91.01
AA	02	1991 Week 05	New software (V3) for RC5921, for France and Italy only.	91.01
AA	03	1991 Week 08	New software (V4) for the benefit of language errors in the Scandinavian version, inversion of the standby signal, surround sound indication changed to mute indication.	91.01
AB	04	1991 Week 15	Introduction of the FL1.1 layout in the FL1.0 and new software (V7 + V8) for child lock solution.	91.02
AB	05		Temporary SSP 3104 317 1116.9 + LED block 4822 466 93009.	91.02
AB	06	1991 Week 41	Introduction 2nd tuner PIP layout.	91.03
AC	07	1991 Week 45	Introduction .3 LSP and introduction of NTSC geometry panel.	91.02
AC	08	1991 Week 48	New software (V15), 1 language cluster, option code modified.	91.02
AD	09	1992 Week 03	Introduction SSP' layout (automatic 16/9 recognition) + introduction ECO NICAM module.	
AD	10	1992 Week 03	FL1.0 SAT, SSP' layout (automatic 16/9 recognition and Y/C on scart).	