

Service
Service
Service

FL1.1

AB

91.04

Service Information

Overview of the manual and AG codes of chassis FL1.1

Correction

MANUAL CODE	AG CODE	DATE	REASON	SERVICE INFORMATION
AA	00	start		
AA	01	1991 Week 34	Breathing picture	91.05 4822 727 19028
AA	02	1991 Week 38	New software (V16) for STU communication	91.05 4822 727 19028
AA	03	1991 Week 39	New layout High end-box ADC + earthing structure modified in the 28ML and in week 9142 also in the 25ML and 33ML	91.02 4822 727 18954
AA	04	1991 Week 41	Introduction 2nd tuner PIP layout	91.01 4822 727 18871
AA	04	1991 Week 42	New PIP tuner	91.03 4822 727 18955
AB	05	1991 Week 45	Introduction .3 LSP and introduction of NTSC geometry panel (definite introduction of the earthing structure modification)	91.05 4822 727 19028
AC	06	1992 Week 03	Introduction SSP' layout (automatic 16/9 recognition) + introduction ECO NICAM module	