

Service
Service
Service

FL1.2

AA

91.03

Service Information

Overview of the manual and AG codes of chassis FL1.2

Correction

MANUAL CODE	AG CODE	DATE	REASON	SERVICE INFORMATION
AA	00	start		
AA	00	1991 Week 42	New PIP tuner	91.01 4822 727 18952
AA	01	1991 Week 43	Good connection of degaussing coils	91.02 4822 727 19005
AB	02	1992 Week 03	Introduction SSP' layout (automatic 16/9 recognition and Y/C on scart)	