

NOTES & ERRATA

25W STEREO BOOSTER

(January 1979, File No. 1/SA/61); The switch wiring diagram on page 42 was not compatible with the overlay diagram on the same page, and also implied the wrong switch rotation. A corrected diagram is reproduced here.

