

Notes & Errata

Stereo Digital-To-Analog Converter (September-November 2009): the TOSLINK receivers can exhibit instability in some cases, resulting in noise in the audio outputs under no-signal conditions. The cure is to increase the 33pF capacitors between pins 1 & 2 of each TOSLINK receiver to 100pF.

Note also that not all Philips remote control codes use the RC5 protocol. If you set a universal remote control to a Philips code but the DAC does not recognise it, try a different code. You may have to go through several before you find one which works.