

• I noticed that the Parts List for the “\$149 Digital Stereo Amplifier” (December 1987) gives the value for trimmers R55 and R63 as 100,000 ohms, while the schematic gives them as 10,000 ohms. Which is correct?

Walter Montgomery
Baltimore, MD

Go with the 10,000-ohm value. The 100,000 ohms given in the Parts List is a typo.—Ed.