

HEART RATE MONITOR (April 1981, 2/MS/58): An error appears on the PC board overlay diagram on page 57 of the April issue. IC5 is shown as a 16-pin device, when in fact it is only a 14-pin package. The IC should be located such that pin 1 of the IC coincides with the pin "1" shown on the overlay. The two spare pads at the end of the IC should be joined together with a link across the width of the IC, connecting pins 7 and 8 of IC5.