

## **Stepper Motors Uncovered (2)**

**December 2003, p. 54-63,  
020127-2**

On the printed circuit board overlay, the symbols for FETs T1-T16 have been printed the wrong way around. The FETs devices should be mounted the other way around.