

Super-9 Stereo FM Radio, November & December 2019: the BB156 varicap used in this design has been discontinued and may become difficult to obtain. The 1SV304TPH3F varicap, still in production, is a suitable replacement. Also the Jaycar catalog code given for potentiometers VR1 & VR6 in the parts list on page 36 of the November issue is wrong. They should be Cat RP7510, not RP7610. Finally, in the alignment procedure described on page 67 of the December issue, where it says to adjust transformer T2, it should instead read inductor L6.