

Telephone exchange

(January 1986, p.1-54)

Capacitors C₆₁ and C₆₂ are shown the wrong way around on the PCB lay-out in Fig. 3; the circuit diagram in Fig. 2 is correct.