• The Fig. 3 etching-and-drilling guide for "A Battery Charger Controller" (November 1987) has an error in it. There should be a connecting trace or wire between the cathode of D1 and the cathode of D5. Without this connection, no +12 volts dc will be applied to the relay's coil.

Ed Drennan
Agincourt, Ontario, Canada

(Continued on page 94)