3 × 3 ALARM ALTERATION

I was glad to see my article "3 × 3 Alarm" in the February issue of **Popular Electronics**. I have noticed one small error in the parts placement diagram on page 99. The outline of the SCR is reversed 180°. The flat side of the outline should be toward S1. The lead markings are correct, so the readers shouldn't have too much trouble with it.

Richard Hampton