


D1280 Calibration (Cont'd)



FUNCTION CHECKS

8. Restore signal. Turn REGENERATION CCW. Push PHASE switch repeatedly; there should be little or no change in gain.
9. Push REPEAT HOLD switch repeatedly. Watch for single-point deformation of waveform.
10. Push PHASE switch and observe the phase change on the scope.
11. Remove signal from K5. Turn REPEAT HOLD off. Signal should now disappear.

JPD-11/83



<http://www.adadepot.com>