

October 13 1998

## TO: ALL EDUCATIONAL DISTRIBUTORS – U.S., CANADA & EXPORT

## SUBJECT: RECOMMENDED SPARE PARTS LIST FOR EDUCATIONAL PRODUCTS

The following lists detail the recommended spare parts each distributor should have in stock to provide quality service to our end customers. The lists are collated by product series, and include the part numbers for both new and refurbished (when available) units.

Rauland-Borg has committed to 24-hour turn around on all repairs, and the quantities recommended reflect this. Units that have been exchanged in the field should be returned for repair as soon as possible to ensure a verified inventory of working units.

IELECENIEK 1100					
	urt Number <u>ecommended</u>	<u>Refurbished Number</u>	<b>Description</b>		
	CTL1	9776	Relay Board		
1	TC4160 Use with TCIV, TCV, & TC2	9711 100	Intercom Module		
1	2524	9793	Master Clock		
2	TC4130	9790	Switchbank		
2	SW25/TC4110 Use with TCIV, & TCV	9791	Switchbank		
1	6400		24V Power Supply		
1	Firmware	9558	Firmware		
TELECEN	NTER <sup>®</sup> 2100				
1	TC2190	9782	Control Card		
1	TC2195	9794	System Analog Card		
1	TC2114	9779	SLC Card		

## **TELECENTER<sup>®</sup>1100**

1	TC2113	9778	3 Wire SLC
1	TC2150	9783	MSM Card
1	TC4182 Use with TCIV & TCV	9786	COA Card
1	TC4190 Use with TCV	9744	DTMF Card
1	TC2120	9780	Relay Card
TELECEN	TEDA IV		
TELECEN 1	TC4411	9737	CPU3
1	TC4410	9708	CPU2
1	9542		MIO Card
1	TC4150	9710	LLM Board
1	EH0001		12 V Hybrid
	a Firmware	9550 & 9552	Firmware
l e	a Firmware	9550 & 9552	Filliwale
		9550 & 9552	Filliwale
TELECEN		9798	CPU
TELECEN	TER® V		
TELECEN 1	<b>TER® V</b> TC4412	9798	CPU
TELECEN 1 1	<b>TER® V</b> TC4412 TC4195	9798 9740	CPU CIO Card
TELECEN 1 1 1	<b>TER® V</b> TC4412 TC4195 TC4155	9798 9740	CPU CIO Card LLM Board
TELECEN 1 1 1 1	<b>TER® V</b> TC4412 TC4195 TC4155 TC41058	9798 9740	CPU CIO Card LLM Board 12V Hybrid
<b>TELECEN</b> 1 1 1 1 1 1 1	<b>TER® V</b> TC4412 TC4195 TC4155 TC41058 TC4196	9798 9740	CPU CIO Card LLM Board 12V Hybrid Relay Board
<b>TELECEN</b> 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<b>TER® V</b> TC4412 TC4195 TC4155 TC41058 TC4196 TC4192 <b>TER® STARPLUS</b> TCKS1401	9798 9740	CPU CIO Card LLM Board 12V Hybrid Relay Board Ringback Module
<b>TELECEN</b> 1 1 1 1 1 1 1 1 1 <b>TELECEN</b> 1 <b>MISCELL</b>	<b>TER® V</b> TC4412 TC4195 TC4155 TC41058 TC4196 TC4192 <b>TER® STARPLUS</b> TCKS1401	9798 9740 9739	CPU CIO Card LLM Board 12V Hybrid Relay Board Ringback Module Integration Kit