

## Lightning protection for high-pass filter

Referring to the high pass filters which appeared over my name in *Circuit & Design Ideas* for May, 1980, I would like to draw attention to a desirable addition to the circuit. Two 100k resistors should be placed as shown to act as static leaks, otherwise the capacitors may be damaged by lightning discharges in the area.

(By Mr R. D. Champness, VK3UG, 31 Helms Court, Benalla, Vic 3672.)

