

Model: KP-46S25, KP-46S55, KP-46V35, KP-46XBR25
 KP-53S15, KP-53S17, KP-53S25, KP-53S35
 KP-53S75, KP-53V15, KP-53V25, KP-53V45
 KP-53V75, KP-53XBR25, KP-53XBR35
 KP-53XBR45

No. 502R5

Subject: Replacement of Lenticular Screen. Which are No Longer Available.

Date: December 19, 2001

Symptom:

(116X)

Need replacement of the 46 or 53-inch Lenticular Screen, which is No Longer Available.

Description	Part Number
Lenticular Screen	4-036-466-01
Lenticular Screen	4-036-466-02
Lenticular Screen	4-036-466-11
Lenticular Screen	4-037-360-01
Lenticular Screen	4-037-360-11
Lenticular Screen	4-064-343-01

Solution: Both the Fresnel and Lenticular Screens will need to be replaced with current parts listed below.

Note: Because the Lenticular screen is No Longer Available you can not change the one screen with the new type. Both screens must be replaced with the parts in the table or the picture quality will not be acceptable.

Models: KP-53S15, KP-53S17, KP-53S25, KP-53S35, KP-53V15, KP-53V25, KP-53V45
 KP-53V75, KP-53XBR25, KP-53XBR35, KP-53XBR45.

Description	Part Number
Fresnel Screen	4-070-602-01
Lenticular Screen	4-070-281-01

Continue on next page

Models: KP-46XBR25, KP-46XBR35, KP-46S25, and KP-46S55, KP-46V35

Description	Part Number
Fresnel Screen	4-057-324-02
Lenticular Screen	4-070-279-01