

SONY

Video Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: SLV-P30HF, SLV-70HF, SLV-50, SLV-353UC, **No. 102**
SLV-555UC, SLV-757UC

Subject: VHS Jig Kit

Date: January 19, 1990


Symptom:
(**)

The following is a list of jigs and tools for VHS service.

Solution:

Ref. No.	Description	Part Number
1	Alignment Tape	
	NTSC	H-7099-046-H
	Normal	H-7099-153-H
2	Torque Gauge	H-7099-039-H
3	Torque Gauge, Adaptor	H-7099-035-H
4	Master Plane	H-7099-279-H
5	Reel Disk Height Jig	H-7099-038-H
6	Small Mirror for Adjustment	J-6080-840-A
7	Torque Measurement Cassette For FWD and back tension torque measurement	
	NTSC (VHT-063S)	J-6082-011-A
	PAL (VHT-063SPAL)	J-6082-066-A
8	Torque Measurement Cassette For CUE and REVIEW torque measurement	
	NTSC (VHT-404S)	J-6082-012-A
	PAL (VHT-404SPAL)	J-6082-067-A
9	0.9mm Hexagonal Wrench	H-7099-202-H
10	1.5mm Hexagonal Wrench	7-700-736-05

Note: The Hexagonal wrench with reference number 10 is for SLV-555/757 only.



Reference: HV - 895008

PRINTED IN U.S.A.
CSV-21289-2

VHS
CSV-2