
Notes & Errata

NRZ RECORDING (April 1977, File No. 8/M/11): The hex inverter device required for the circuit is a 7406, not a 7407 as specified.

SOLAR PANEL OFFER (January/March 1979): Due to the imposition of import duty, the price of the 14.4V/4.32W panel offered must now be increased to \$182 including sales tax, or \$160 tax exempt. In either case the figure of \$5 still applies to cover certified postage and handling. The address of Amtex Electronics is Suite 503D, 73 Archer Street, Chatswood, NSW 2067, telephone (02) 411 1323.

INTERSIL ICL7106 DVM KIT (February 1979, File No. 7/M/56): We have been asked to advise readers that the sole representatives for Intersil products in Australia are R & D Electronics of 23

Burwood Road, Burwood, Victoria 3125.

BIPOLAR TRAIN CONTROLLER (February 1979, File No. 2/MC/17): In the wiring diagram at the bottom of page 35, the output connections of the rectifier bridge are shown transposed. The positive output should connect to the 1k pot and the collector of the BD263, not the negative output. The circuit diagram is correct.

AMATEUR RADIO BOOKS (Reviewed in February 1979, page 115): Both of the books mentioned are available from WIA (NSW) Education Services, PO Box 109, Toongabbie, NSW 2146. Both books may also be obtained as part of a more extensive Novice kit, available for \$15.00 posted.