

TRANSISTOR TEST SET (August 1968): The circuit on p. 37 contains a small error. The lead from the "BV" lug of the switch connected to the cathode lug of the diode socket should connect to the "diode" lug of the topmost section of S1, not to the "PNP" lug as shown. The parts list on p. 41 should show the voltage rating of the 2uF electrolytic capacitor as "200VW"; also the 8uF 300VW capacitor listed is not required, and should be removed from the list. ■