

45V 8A Linear Bench Supply, October-December 2019: in the PCB overlay diagram (Fig.6) on page 70 of the November issue, the types and labels for diodes D5 and D6 are swapped. D5 is on the left and should be a 1N5404 type, while D6 is closer to the edge of the board and should be an SB380. The PCBs supplied for this project have the same error on their silkscreen printing. The circuit will still function correctly if both diodes are SB380s.