



	DATE: 03/20/01
Model: TX-DS484, TX-DS575, TX-575X, TX-DS676, TX-DS777	Ref: DTS-Re-EQ-1
<i>Classification: Mandatory</i>	
Problem: Intermittent audio drop out or flutter.	

When a **DTS** program material is being played, it is possible the audio may at some point tend to break-up or flutter. This is not a failure in the product, when the **Re-EQ** setting is left in the **ON** position, it will affect the **DTS** operation. The RE-EQ setting should not be used when playing DTS material. Re-EQ must be **OFF** for DTS to work properly.

"In the parameter setting of Owners Manual, **DTS** was included when using the RE-EQ setting effectively. That is a print error."

No service is required except customer education.