

Service Manual

DVD Home Theater Sound System



SA-HT75P
SA-HT75PC
SA-HT95P
SA-HT95PC
SA-HT75E
SA-HT75EB
SA-HT75EG
SA-HT75EE
SA-HT75GC
SA-HT75GCS
SA-HT75GD
SA-HT75GCP
SA-HT75GN

Colour

(S).....Silver Type

Subject : Correction of Part No. of Spindle Motor Ass'y.

Please use this supplement manual together with the service manual for
Model No. SA-HT75P/PC (Order No. MD0204099C1),
Model No. SA-HT75E/EB/EG/EE (Order No. MD0205134C2),
Model No. SA-HT75GC/GCS/GD/GCP/GN (Order No. MD0206155C3),
Model No. SA-HT95P/PC (Order No. MD0205129C1).

WARNING

This service information is designed for experienced repair technicians only and is not designed for use by the general public.
 It does not contain warnings or cautions to advise non-technical individuals of potential dangers in attempting to service a product.
 Products powered by electricity should be serviced or repaired only by experienced professional technicians. Any attempt to service
 or repair the product or products dealt with in this service information by anyone else could result in serious injury or death.

Panasonic

© 2002 Matsushita Electric Industrial Co., Ltd. All
 rights reserved. Unauthorized copying and
 distribution is a violation of law.

1 Correction of CD Loading Mechanism Parts List

Note:

This part is supplied by SPC.

Ref. No.	Change of Part No.		Part Name & Description	Remarks
	Original	Correction		
CD LOADING MECHANISM				
400	RXQ0749A	RXQ1028	SPINDLE MOTOR ASS'Y	(SPC)

2 Illustration of Spindle Motor Ass'y

