


# PHILIPS CONVERTERS

bergesys@mail.yesic.com



Caps go bad.

Bad connections on voltage regulators.

tip-003 phil

Add heat grease to regulators!

Screw to adjust channel 3 output frequency.

Small plastic filter must be in place in some units to reduce noise levels to the IR receiver.

Plastic buttons can cause problems remove connector ribbon, or replace.