

TV Products Service Bulletin

CSV-1

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: KP-46S15, KP-53S15, KP-61V25, KP-53XBR45, KP-61XBR48 **No. 282**

Subject: New Screw for Mirror Holder **Date:** February 15, 1996

Symptom:
(131) If unit requires rear cover or mirror replacement due to transportation damage.
Please replace screws for Mirror holder Left and Right side.

Solution: New Screw is listed below:

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
	SCREW 4X12	7-685-661-79	SCREW 4X30	7-685-666-71

Qty. of Screws per unit:

KP-46S15, KP-53S15, KP-61V25: 4 PCS
KP-53XBR45, KP-61XBR48: 6 PCS

