

Model: KP-53XBR45, KP-61XBR48**No.** 360**Subject:** Part Number Missing –Front Escutcheon**Date:** June 19, 1998**Symptom:**
(XXX)

The part number for the Front Escutcheon, which is shown on page 106 of the Service Manual, is not listed in the parts list.

Solution: Please add the following part number to the Service Manual.

REF	DESCRIPTION	PART NUMBER
	FRONT ESCUTCHEON	4-050-151-02

