

TV Products Service Bulletin

CSV-1

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: KP-41T15, -46S15, -53S15, -46V25, -53V25,
KP-61V25, -53XBR45, -61XBR48

No. 299R1

Subject: T604 (Transformer, Power Supply) Change

Date: December 4, 1996

Symptom:

(111) The Unit has No power due to Power Supply Failure and requires Q601, Q602 or another component replacement in power supply circuit.

Applicable Serial Number:

KP-41T15: 9000001 ~ 9020800
KP-46S15: 9000001 ~ 9018900
KP-46V25: 9000001 ~ 9004700
KP-53S15: 9000001 ~ 9011400
KP-53V25: 9000001 ~ 9005700
KP-61V25: 9000001 ~ 9003100
KP-53XBR45: 9000001 ~ 9004100
KP-61XBR48: 9000001 ~ 9000700

Solution:

If Serial Number of Unit is within above range when replacing Q601, Q602 or another power supply component.
Please replace T604 (Converter Transformer) at same time.

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
T604	TRANSFORMER, CONVERTER	1-427-864-11	TRANSFORMER, CONVERTER	1-427-864-12 OR -13

Note: Part number for Q601 and Q602 is 8-729-019-49 (2SC4834M).

