

**SONY**

Video Products  
Service Bulletin

Sony Service Company · Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** SLV-353UC/555UC/575UC/676UC/  
757UC/R5UC

**No. 141**

**Subject:** Shaft Ground Assembly Now Available **Date:** January 7, 1991

**Symptom:**  
(\*\*)

The Shaft Ground Assembly, which is included with the Drum Assembly, is now available as a separate part.

**Solution:** Please add the following part number to your service manual:

Ref. No.	Description	Part Number
---	Shaft Ground Assembly	X-2643-202-3

CSV-2 VHS