

SONY

Video Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: SLV-50/70HF/272UC/353UC/373UC/555UC/
575UC/676UC/757UC/R5UC **No. 140**

Subject: Part Number Information - Lapping Tape **Date:** January 7, 1991

Symptom:
(**)

A lapping tape for VHS machines is now available.

Solution: Please update your service manual with the following information:

| Ref. No. | Description | Part Number |
|----------|--------------|--------------|
| --- | Lapping Tape | J-6090-010-A |

Conditions of Use:

- o When the output from the video head is LOW.
- o When the video head is clogged severely, and normal cleaning does not work.

Procedure:

Run the lapping tape for 7 seconds in SP Recording Mode.

Notes:

- o Do not rewind.
- o Use the lapping tape for only 7 seconds. If RF level has not recovered, check the machine for other troubles.

CSV-2 VHS