

- In Fig. 1 of “A miniature LED Beacon” (January 1988), the internal connections going to pins 8 and 2 of the LM3909 should be reversed.

Dan Becker

- To avoid any confusion, please transpose the illustrations (not the captions) for Figs. 3 and 4 in “Choosing Op Amps for Specific Applications” (November 1987).

Charles R. Fischer