

Notes & Errata

**Remote Switch for Car Alarms,
March 1988:** the inductor marked
L2 in the receiver should have an
F29 slug, not F16 as specified.