

ERRATA

A. E. Richmond, author of the article "Rapid Attenuator Calculations Using the Vector Slide Rule" in the December 1950 issue, reports the following errors on page 46:

The formula at the middle of the column should have the fraction bar inserted, to read $\theta = \cosh^{-1} \sqrt{Z_1/Z_0}$.

Step 4 of the calculation procedure should read "To determine this minimum loss in decibels, multiply θ by 8.686. Use Scales C and D."

AUDIO