
Notes & Errata

Walkaround Throttle, Ask Silicon Chip, page 93, May 1995: the suggested wiring diagram for a centre-tap transformer shows the $10\mu\text{F}$ capacitor near the 7812 reverse biased. The capacitor's negative connection should go to the centre pin of the 7812. **SC**